March Troubleshooting Problem

QUESTION: After performing the troubleshooting procedure noted, what is your next step in solving this problem?

ANSWER: The next step is to replace the Indoor Blower Delay Relay because the M1 and M2 contacts are stuck. When the call for heat was terminated and the circuit was broken to the IBDR coil, the contacts should open to shut the blower motor down after a delay.