

## May Troubleshooting Problem

**QUESTION:** After shutting the system down and recovering the refrigerant, what did the technician find in the section of liquid line piping that he checked?

**ANSWER:** The technician found that the material in the molecular sieve drier, due to a break in the drier screen, had been forced through the liquid line, causing a restriction at the bends near the indoor coil.