

May Troubleshooting Problem

QUESTION: After following manufacturer troubleshooting procedures, what is the next step you need to take in servicing this equipment?

ANSWER: The next step is to replace the evaporator temperature sensor. When checking a sensor of this type for resistance to ground, a zero ohms reading indicates that the sensor has failed.