

## March Troubleshooting Problem

**QUESTION:** After test cycling the unit and consulting the wiring diagram, what is the underlying cause behind this situation that is preventing the blower motor from operating in the heating mode?

**ANSWER:** The previous technician replaced the single-pole contactor with a two-pole contactor. This allowed the cooling mode to operate normally, but it prevented the indoor blower motor from receiving operating voltage in the heating mode.