

September Troubleshooting Problem

QUESTION: After your evaluation of the equipment, what is the next step you need to take in order to achieve proper airflow in this system?

ANSWER: The solution to this problem is to change the wiring connection on the indoor blower motor from low speed to medium-low. Our temperature rise test showed insufficient airflow, with the differential being 5°F higher than the manufacturer's specification.