

July Troubleshooting Problem

QUESTION: After using your digital ammeter to check the dual run capacitor, what is the next step you need to take in repairing this equipment?

ANSWER: The dual capacitor needs to be replaced. Our current draw tests showed that there was more than one tenth of an amp difference between test of the start winding wire and the run/common wires, which indicates that the capacitor is not within the allowable tolerances regarding its microfarad rating.