

Line 1

Line 2

Operating  
Control

Overload

R

S

Run  
Cap

PTCR  
T

