

January Troubleshooting Problem

QUESTION: After completing your evaluation of the ice machine, which component needs to be replaced?

ANSWER: We need to replace the control board. Since all the other control relays on the board were providing operation to the other components needed during the harvest sequence, and no voltage was applied to the connector at the air compressor, it proved that the control board was the problem.