

July Troubleshooting Problem

QUESTION: After doing an entering and leaving test at the reversing valve tubing connections, what is the next step you need to take to repair this equipment?

ANSWER: The 15°F temperature difference measured between the line from the indoor coil entering the reversing valve and the line exiting the valve to the compressor shows that it, and not the compressor, is the source of the problem. It is leaking internally and needs to be replaced.