

March Troubleshooting Problem

QUESTION: What is the next step you need to take in regard to this situation?

ANSWER: The equipment is undersized for the store's heat load.